TEST REPORT

Name of Sample	GPS Tracker
Model(s)	MT200X
Brand Name	Twin mask
Client	ShenZhen Megastek Electronics Co. Ltd.
Address of Client	RmB1111,Niulanqian Building,Minzhi Road,Longhua Town,Baoan District,Shenzhen,China.
Inspection Classification	Commissioned inspection
Tested Item(s)	Maximum Tensile Test

SHENZHEN TOBY TECHNOLOGY CO.,LTD.

Address:1/F., Building 6, Rundongsheng Industrial Zone, Longzhu, Xixiang, Bao'an District, Shenzhen, Guangdong, China
TEL:86-755-26509301/02 FAX：86-755-26536985
Internet: www.tobylab.cn E-Mail:toby@tongbiao.com

Shenzhen TOBY Technology Co.,Ltd.
1/F., Building 6, Rundongsheng Industrial Zone, Longzhu,
Xixiang, Bao'an District, Shenzhen, Guangdong, China
Tel：86-755-26509301/02 Fax： 86-755-26536985
Http: // www.tobylab.cn

Name of Sample	GPS Tracker	**Brand Name**	Twin mask
Model(s)	MT200X	**Quantity of sample**	6 Pcs
Client	ShenZhen Megastek Electronics Co. Ltd.		
Address of Client	RmB1111,Niulanqian Building,Minzhi Road,Longhua Town,Baoan District,Shenzhen,China.		
Manufacturer	ShenZhen Megastek Electronics Co. Ltd.		
Address of Manufacturer	RmB1111,Niulanqian Building,Minzhi Road,Longhua Town,Baoan District,Shenzhen,China.		
Inspection Classification	Commissioned inspection	**Tested Item(s)**	Maximum Tensile Test
Date of receipt Sample	Oct. 20, 2021	**Finished Date**	Oct. 26, 2021
Ambient temperature and humidity :	24～26℃, 45～70% R.H.		
Test standard	1.According to customer requirements		
Remarks: N/A			
Conclusion of test	The tested item conformity above standard requirements. Conclusion：Complied. Stamp: Issue date:		

Report by (Jason Xu)	: Jason Xu	**Oct. 26, 2021**
Checked by (Tony Xiong)	: Tony Xiong	**Oct. 26, 2021**
Approved by (Justin Zhang)	: Justin Zhang	**Oct. 26, 2021**

Sample describing

1、Product describing: The appearance of the sample is intact and no damage.
2、Sample parameters: --
3、The testing is according to customer's requirements.

Possible test case verdicts:
- test case does not apply to the test object: N/A
- test object does meet the requirement: P (Pass)
- test object does not meet the requirement: F (Fail)

Remark：
1、The test results presented in this report relate only to the object tested.
2、The results relate only to the items tested.

Shenzhen TOBY Technology Co.,Ltd.
1/F., Building 6, Rundongsheng Industrial Zone, Longzhu,
Xixiang, Bao'an District, Shenzhen, Guangdong, China
Tel：86-755-26509301/02 Fax： 86-755-26536985
Http: // www.tobylab.cn

Maximum Tensile Test

Serial Number	Test methods/conditions	Testing requirements	Test Results
1	Wrist strap closed, vertical gravity test	The positioning foot ring wristband is closed and suspended in the air. The vertical gravity is applied horizontally. How much weight will break the wristband	The weight of 104.33KG causes the wristband to break, After completing the tests
2	The wristband is released, placed face up, and weight is applied to one of the wristbands vertically placed at 90 degrees	Position the anklet facing upwards, and place the single wristband 90 degrees vertically. Apply weight to the single wristband vertically, and how much weight causes the wristband to disconnect	The weight of 92.37KG causes the wristband to break, After completing the tests
3	The wristband is released and the back is placed upwards. Weight is applied to a wristband that is placed vertically at 90 degrees	Position the anklet facing back, and place the single wristband 90 degrees vertically. Apply weight to the single wristband vertically, and how much weight causes the wristband to disconnect	The weight of 92.31KG causes the wristband to break, After completing the tests
Conclusion			
After completing the three tests, the metal inserting clip connecting the lock is not damaged and broken			

Shenzhen TOBY Technology Co.,Ltd.
1/F., Building 6, Rundongsheng Industrial Zone, Longzhu,
Xixiang, Bao'an District, Shenzhen, Guangdong, China
Tel：86-755-26509301/02 Fax： 86-755-26536985
Http: // www.tobylab.cn

Photo

Photo 1 Appearance of EUT



Photo 2 Appearance of EUT



Photo 3 Test photos



Photo 4 Test photos



Photo 5 Test photos



Photo 6 Test photos




Photo 7 Test photos





Photo 8 Test photos



***** END OF REPORT*****

Shenzhen TOBY Technology Co.,Ltd.
1/F., Building 6, Rundongsheng Industrial Zone, Longzhu,
Xixiang, Bao'an District, Shenzhen, Guangdong, China
Tel：86-755-26509301/02 Fax： 86-755-26536985
Http: // www.tobylab.cn

DECLARATIONS

1、The issuing laboratory is accredited by China National Accreditation Service(CNAS) For Conformity Assessment under accreditation certificates No.L5813.

2、Any photocopies or part photocopies of the test report are forbidden without the written permission from TOBY.

3、Objections to the test report must be submitted to TOBY within 10 days.

4、The test report is invalid without the official stamp of TOBY.

5、The test report is invalid of altered.

6、The results relate only to the items tested.

7、The laboratory is with responsibility for the received sample and the result of the test can only reflect the evaluating of the sample. Therefore, the laboratory does not bear any liability for loss direct or indirectly caused to applicant by this result of the report.

8、“P” means“pass”,“F”means“fail”,“N” or“—”means“not applicable”,“/ ”means“not test” .